

From: ["COLLINS Jamie" <Jamie.Collins@state.or.us>](mailto:Jamie.Collins@state.or.us)

To: davidb@hydroconllc.net
charles.schwarz@odot.state.or.us
["NOWICKI Teresa" <Teresa.NOWICKI@state.or.us>](mailto:Teresa.NOWICKI@state.or.us)
["Fowlow, Jeffrey" <Fowlow.Jeffrey@epa.gov>](mailto:Fowlow.Jeffrey@epa.gov)

Date: 3/4/2019 10:08:57 AM

Subject: Backfill clearance - N side, grid lines 240-320

Attachments: Backfill Approval - 4 Feb 2019 - N Side, Grid Lines 240-320 (Westbound Lanes).PDF

Backfill from 240-320 is approved. Electronic copy attached. David and I discussed the need for a bit more excavation at the shoreline to get at the residual contamination indicated by sample 40,310,20. Jamie

Jamie Collins
State On-Scene Coordinator
Eastern Region
Oregon Department of Environmental Quality
475 NE Bellevue Dr., Suite 110
Bend, OR 97701
541-633-2010 (office)
541-321-3124 (mobile)
541-388-8283 (fax)

Unsure when and how you should report an oil spill or release of hazardous materials in the State of Oregon? Visit <https://www.oregon.gov/deq/Hazards-and-Cleanup/env-cleanup/Pages/How-To-Report-A-Spill.aspx>